

<b>Application</b>	HVAC
<b>Problem</b>	Components were beginning to fail. Sheaves fractured and the fan shaft and blades corroded, increasing the potential for major damage to the tower.
<b>Solution</b>	Replaced failing parts with Marley® components, including X7 fan, bearings, fan shaft, belt, basin covers, motor, sheaves and bushings.
<b>Results</b>	Tower restored to safe and efficient operating level; tower life extended



Contact your Marley representative to identify parts for other manufacturers' towers: [spxcooling.com/relocator](http://spxcooling.com/relocator)

**SPX COOLING TECHNOLOGIES, INC.**

7401 WEST 129 STREET  
 OVERLAND PARK, KS 66213 USA  
 913 664 7400 | [spxcooling@spx.com](mailto:spxcooling@spx.com)  
[spxcooling.com](http://spxcooling.com)

CCS-FR-17 | ISSUED 08/2017  
 COPYRIGHT © 2017 SPX CORPORATION

In the interest of technological progress, all products are subject to design and/or material change without notice.

