

Application	Process Cooling
Problem	Over time, PVC heat transfer fill undergoes changes from environmental exposure that impacts its performance and original design. Inspection of this tower confirmed brittle fill, sagging and biological fouling, requiring replacement.
Solution	Marley® MBX replacement fill packs with bottom supports and integral louvers allowed simple component replacement, saved contractor time, minimized outage duration and restored tower operation.
Results	Extended tower life.



Contact your Marley representative to identify parts for other manufacturers' towers: spxcooling.com/relocator

SPX COOLING TECHNOLOGIES, INC.

7401 WEST 129 STREET
 OVERLAND PARK, KS 66213 USA
 913 664 7400 | spxcooling@spx.com
spxcooling.com

CCS-BSFP-17 | ISSUED 08/2017
 COPYRIGHT © 2017 SPX CORPORATION

In the interest of technological progress, all products are subject to design and/or material change without notice.

